## MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible: yes \_\_\_\_\_ no \_\_\_\_

sperty Name: Frame Farmhouse	Inventory Number: WA-II-483
Address: 8617 Sharpsburg Pike	Historic district: yes X no
City: Fairplay Zip Code: 21733	County: Washington
USGS Quadrangle(s): Funkstown	
Property Owner: Clayton and Patricia J Haworth Ta	ax Account ID Number: 008317
Tax Map Parcel Number(s): 45 Tax Map Number	: 62
Project: Intersection Improvements, MD 65 and MD 68 #WA142A21 Agency:	Maryland State Highways Administration
Agency Prepared By: TRC Garrow Associates Inc	
Preparer's Name: Geoffrey Henry	Date Prepared: 10/25/2005
Documentation is presented in: Frame Farmhouse MIHP form prepared by Joe Ge	etty (1983)
Preparer's Eligibility Recommendation: Eligibility recommended	X Eligibility not recommended
Criteria: A B C D Considerations: A B	
Complete if the property is a contributing or non-contributing resource to	
Name of the District/Property:	
Inventory Number: Eligible: yes	Listed: yes
te visit by MHT Staf yes X _ no Name:	Date:
Description of Property and Justification: (Please attach map and photo)	
Location and Setting This house is located on the east side of MD 65, 2/10 mile south of MD 68, in the vion the road and is bordered on the north and on the south by driveways.	llage of Lappans. The house stands directly
Description This 2-story, 5-bay, gable-roofed frame house is covered with vinyl siding, has a me fieldstone foundation. The main façade has a central entrance with rectangular transcriptors. The 2/2 double-hung sash windows have arched upper sash and have ramped the southwest corner. There is a 2-story gable-roofed wing on the rear of the house with the southwest corner.	om and a hipped-roof porch with replaced lintels. There is a polygonal window bay on
Condition and Alterations/Additions  This house is in fair condition and has had several exterior alterations including the a original porch posts, and removal of a 2-story incised porch on the south elevation or	
MARYLAND HISTORICAL TRUST REVIE	
Eligibility recommended Eligibility not recommended	1
Criteria:ABCD Considerations:A	BCDEFG
MHT Comments:	
	=(./
Reviewer, Office of Preservation Services	5/4/06 Date
1173 to A	Inla
Reviewer, National Register Program	Date

#### NR-ELIGIBILITY REVIEW FORM

### WA-II-483

#### Frame Farmhouse

Page 2

rm, the ramped window lintels also had a central keystone, which has since been removed.

Historical Background

According to tax records, this house dates from 1886.

Evaluation

The Frame Farmhouse is not associated with a known event or series of events significant on the local, state, or national level and is not eligible for listing in the National Register of Historic Places (NRHP) under Criterion A.

The Frame Farmhouse is not associated with the life of an individual significant on the local, state, or national level and is not eligible for the NRHP under Criterion B.

The Frame Farmhouse does not embody the characteristics of a style, period, or method of construction, and is not the work of a known architect or builder. The Frame Farmhouse has had numerous alterations on its exterior and is not NRHP-eligible under Criterion C.

The Frame Farmhouse is not NRHP-eligible under Criterion D.

MARYLAN	D HISTO	DRICAL	TRUST	REVI	E							
Eligibility r	ecommen	ded		Eli	gibility not recommen	ded						
Criteria:	A nents:	B	c	D	Considerations:	A	В	c	D	E	F	G
_	Review	er, Offic	e of Pres	servatio	n Services			Date			-	
	Revie	wer, Nat	tional Re	gister l	Program			Date				



WA-11-483 FRAME FARMHOUSE 8617 SHARPSBURY PIKE WASHINGTON AUTOMAN 2 7160 G. HENRY 10-2005 VION FROM ROAD LOCKING NE (No. 11A) BSUMC

WA-II-483 Frame Farmhouse

Mid-19th century

Lappans

Private

The Frame Farmhouse is a two-story, five-bay by one-bay T-shaped structure. It is more ornamented than many houses in the area including wooden window frames with molded lintel and wood ornamentation resembling the keystone. The main facade has a full-length, one-story front porch on turned posts and a molded cornice. There is a central entrance and a three-sided bay window on the first floor. The house has a stone foundation and a sheet metal roof. There are ornamental brick chimneys at the gable ends of the main section and half way back the wing. A modern chimney is located at the rear of the wing. The exterior is covered in German siding painted gray with the trim painted white.

1/25

Survey No. WA-II-483

Magi No.

DOE \_yes \_no

# Maryland Historical Trust State Historic Sites Inventory Form

1. Name	e (indicate pr	eferred name)		
historic	gris-layed-sco ye salodwy galbol ga e	tac-evil cin-car uy howese in the vre	m el mandomen en drombuted than mo	ri enr Cross el Ji
and/or common	Frame farmhouse	noivalmenta book	this still tealor.	
2. Loca		orapino area series	nor. The house h	ino present
street & number	east side of Rt.	65, .2 mile south of	Lappans Road	not for publication
city, town Lap	pans	vicinity of	congressional district	sixth
state Maryla	and	county	Washington	
3. Class	sification	n o a geoma-weet si	A consequent at bro-	amagna in
district X_ building(s) structure	Ownership public private both Public Acquisition in process being considerednot_applicable	Status  X occupied  unoccupied  work in progress  Accessible  yes: restricted  yes: unrestricted  no	Present Use agriculture commercial educational entertainment government industrial military	museum park x private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names an	d mailing addresse	s of <u>all</u> owners)
name	Harnett			
street & number			telephone n	0.:
city, town		state	and zip code	
5. Loca	tion of Leg	al Description	n	
courthouse, regist	try of deeds, etc. Was	hington County Court	house	liber
street & number	Washington Stree	t		folio
city, town Hag	gerstown		state	Maryland
6. Repr	esentation	in Existing	Historical Surv	reys
itle				
date			federal sta	te county loca
depository for sur	vey records			
city, town			state	

7.	Description	ì
TT. 11 TT.		

Survey No. WA-II-483

Condition excellent	deteriorated	Check one unaltered	Check one original site
good fair	ruins unexposed	altered	moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame farmhouse is a two-story, five-bay by one-bay T-shaped structure. It is more ornamented than many houses in the area including wooden window frames with molded lintel and wood ornamentation resembling the keystone. The main facade has a full-length, one-story front porch on turned posts and a molded cornice. There is a central entrance and a three-sided bay window on the first floor. The house has a stone foundation and a sheet metal roof. There are ornamental brick chimneys at the gable ends of the main section and half way back the wing. A modern chimney is located at the rear of the wing. The exterior is covered in German siding painted gray with the trim painted white.

The frame farmhouse is located on the east side of Rt. 65, .2 mile south of Lappans Road in Lappans. It rest among a cluster of properties dating from the latex 19th century to the present time. The main facade faces west.

The size of this structure, the ornamentation, and the first floor bay window give the appearance that the property was probably used for a commercial purpose, probably as a store. In comparison with other properties in the area, the ornamentation is quite notable. Also, the T-shape differentiate this property significantly in the rural countryside. One side of the wing has a double story porch similar to those found on the L-shaped houses.

The property has a summer kitchen of period design. It also has a stable with a gable roof and ornamental trim on the peak of the roof.

8.	Significance
-	orginillounioc

Survey No. WA-II-483

Period Areas of Significance— prehistoric archeology-prehistoric 1400–1499 archeology-historic 1500–1599 agriculture 1600–1699 architecture 1700–1799 art 1800–1899 commerce 1900– communications		community planning
Specific	dates	Builder/Architect
check:	Applicable Criteria:A and/or	BCD
	Applicable Exception:	BCDEFG
	Level of Significance:	national state local

This structure displays an excellent example of the Victorian period's method of ornamenting the traditional farmhouse found in this region. It is a contributing building in the Lappans Survey District.

# 9. Major Bibliographical References

10.	Geograp	hical Data						
Quadran	of nominated prope	complete UTM refer		Quadrangle scale				
AZone		Northing	B Zone	Eas	ting	Northing		
C E G			D					
Verbal	boundary descript	ion and justification			1			
	states and counti	es for properties overl		ounty	boundaries			
state		code	county			code		
	Form Pro	epared By	County			0000		
name/titl	e Joe Getty							
organiza	tion Maryland	Historical Trust	d	ate	May 1983			
street &	number 21 Stat	e Circle	te	elepho	one			
city or to	wn Annapolis		s	tate	Maryland			

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





- 1. Frame Farmhouse WA-II-483
- 2. Washington County, Maryland
- Joe Getty
   May 1983
- 5. Maryland Hist. Trust, Annapolis, Md.
- West & south elevations; camera facing northeast
- 7. 1/1